

TUNEUP PROGRAM COSTS

	Services Provided	Total Fee	Customer Share	IRWD Share
Evaluation (required)	 1 hour landscape evaluation Irrigation controller reprogramming (base schedule) and customer training Eligible customers may elect to proceed with Tier 1 or 2 repairs 	\$275	\$137.50	\$137.50
Tier 1	 PVC anti-siphon valve replacement, valve leak repair, or valve wiring repair (1 per site). Raise, replace, and adjust sprinkler heads and nozzles, up to 6 per site. 1 lateral irrigation line repair on PVC. Maximum of 4 feet. Flush and replace drip coupling and emitters, up to 6 per site. 	\$200	\$100	\$100
Tier 2	 PVC anti-siphon valve replacement, leak repair, wiring repair, 2 to 3 per site. Raise, replace, and adjust sprinkler heads and nozzles, 7 to 12 per site. 2 lateral irrigation line repairs. Maximum of 4 feet. Flush and replace drip coupling and emitters, 7 to 12 per site. 	\$350	\$175	\$175
	Itemized Cost for Additional Components (after Tier repairs)			
	PVC Anti-Siphon Valve Replacement	\$75/ea	\$37.50	\$37.50
	Raise/Replace Sprinkler Body	\$15/ea	\$7.50	\$7.50
	Replace Nozzle (HE or same precipitation rate nozzle)	\$5/ea	\$2.50	\$2.50
	Replace HE Stream Nozzle (R-VAN or MP Rotor)	\$10/ea	\$5	\$5
	Retrofit Rotor (New Body for HE Stream Nozzle)	\$25/ea	\$12.50	\$12.50
	Irrigation Line Repair (per 4-foot section, not to exceed two additional sections)	\$75/ea	\$37.50	\$37.50
	Drip Irrigation Emitter/Coupler	\$5/ea	\$2.50	\$2.50