


# SITE MAP



Revised - Sept 2011\*

**LEGEND**


- Irrigation Water Well
- Irrigation Water Pipeline
- Irrigation Water Purification Plant

**SGU** Shallow Groundwater Unit  
**ET** El Toro

\*TCE concentration contours per:  
 Groundwater Monitoring and System Operations  
 Data Summary Report, September 2011, Figure 2.

Installation Restoration Program Sites 18 and 24  
 Groundwater Remedy March 2010 Event 15.

Report prepared by Weston Solutions, Inc. for the  
 Base Realignment and Closure  
 Program Management Office West  
 Naval Facilities Engineering Command.



**VOCs LEGEND**

- Less
- More



## EL TORO GROUNDWATER REMEDIATION PROGRAM